

Q.C. WELDER WITH PIT DEPTH GAUGE

The Q.C. welder with pit depth gauge measures pit depth, weld height and outside "high-low". The stainless steel pit depth gauge mounts on the end of the Q.C. welder's gauge housing and displays in English measurements.





Precise: Measures as small as 1/64" (0.4 mm)

Easy: Simply slide the pit depth gauge over the

Q.C. gauge and take the reading



Measurement 1/64 th or .4 mm increments.

PART NO	DESCRIPTION	WEIGHT	
D253E	English Q.C. welder with pit depth gauge	0.2 lbs.	0.10 kg
D253E-BOX	English Q.C. welder with pit depth gauge (box of 10)	2.0 lbs.	0.90 kg

